



Wrist-Strap Tester Calibrator

WSC-QC

Description

This tester calibration unit is designed to simplify the process of calibrating wrist-strap testers. This unit allows the user to quickly and easily verify whether a tester is operating within specifications. The tester calibration unit is a passive device and requires no power source. Light and audible signals verify results on the unit you are testing.

Testing

Connect the 2 leads to the banana sockets at the top of the calibration unit. Connect one of the leads to the banana socket of the WST-1 and touch the metal plate of the WST-1 with the other. Then you can check low fail etc moving around the test knob on the calibrating unit.



Specifications	
Fail Low	715 kilohm
Pass Low	785 kilohm
Pass High	33 megohms
Fail High	37 megohms
Accuracy	±10%
Dimensions	96mm L x 61mm W x 40mm H

Standards

All test instruments are manufactured to the very highest quality, allowing qualification to council directives 89/336/EEC. All items are CE approved.

Test instruments are supplied with a calibration certificate. Calibration testing is recommended on a regular basis (annually).

